

Imray Correction Notice

283

30 August 2012

Chart 2800+3 WGS 84

Edition Mar 2004

Date of printing Mar 2004

The following corrections should be noted:

1 Oban (Plan A) (re-instated - see correction ILNW 102/08)

Delete Lt 2F.G(vert) in 56°24'·69N 5°28'·65W. (ILNW 117/05)

2 Oban (Plan A)

Delete Lt 2F.G(vert) in 56°24'·66N 5°28'·77W. (ILNW 184/05)

3 Loch Feochan (Plan B)

Delete all con, can buoys and Bns in the channel east of Ardentallan Point and insert Igd *Buoyed*. (ILNW 257/05)

4 Firth of Lorn, Loch Spelve

Amend Lt to Fl.G.5s3m2M in 56°23'·24N 5°41'·90W. (ILNW 481/06)

5 Oban, Dunollie (Plan A)

Amend Lt range to 8·6M in 56°25'·37N 5°29'·04W and amend sectors to **351°-G-020°-W-047°-R-120°-W-138°-G-143°**. (ILNW 90/07)

6 Oban Bay (Plan A)

Re-insert Lt 2F.G(vert) in 56°24'·69N 5°28'·65W. (ILNW 102/08)

7 Oban Bay (Plan A)

Insert Igd *Seaplane Operating Area* centred on 56°25'·04N 5°29'·25W. (ILNW 103/08)

8 Firth of Lorn, Bogha Nuadh and Bogha Ghair (Correction amended - see ILNW 312/12)

Move Lt buoy **Bono Rock** Fl(4)R.12s in 56°16'·23N 5°40'·97W to 56°16'·49N 5°40'·50W. (ILNW 149/08)

9 Sound of Luig

Insert W card Lt buoy Q(9)15s in 56°16'·20N 5°41'·25W (ILNW 112/09)

10 Loch Spelve entrance

Insert dangerous rk awash sym in 56°23'·14N 5°41'·95W (ILNW 262/10)

11 Kerrara Sound, Heather Island

Insert Lt Fl.R.2·5s11m2M in 56°24'·41N 5°30'·24W (ILNW 475/11)

12 Bogha Ghair

Replace R can Lt buoy Fl(4)R.12s with E card pillar Lt buoy Q(3)10s in 56°16'·49N 5°40'·50W (ILNW 312/12)

13 Luig, Fraoch Eilean northwards

Insert dangerous underwater rk sym in 56°14'·89N 5°39'·33W (ILNW 359/12)